SIGNAL STRENGTH MEASUREMENT TEST
Coordinates of priniciple headend: LATITUDE: 38 D 54 M 348 LONGITUDE: 28 D 1/ M 498 CHIEF TECH.
TIME OF DAY OF TEST 1:15 TEMPERATURE: 75 DEGREES FAHRENHEIT
Otreet address of principal headends 706 5. ROYAL ANE. FRONT ROYAL, VA. 22650
Off-air channel number: 60 Call Letters: WYVN
Type of antenna used: LOG PERIODIC, LINDSEN 10LED-13 FM/N
Antenna Height Above Ground: 60 feet
Measured visual level: -5 dBmv O/N: LEVEL TO LOW TO GET GOOD READING.
Calculated leveli dBmv (See Conversion Chart)
Please give a detailed description of the reception, denoting any glosts, electrical noise, color smearness, etc. WITH YAGI ANTENNA & PROCESSOR & QUALITY PICTURE - 15 OBTAINABLE.
Type of test equipment: SIM TEST SET Model number: FSM-/ Menufacturer's name: ALGUTEN Attach a specific of the test agultament
Manufacturer's name: HUANTEN Attach a specific of the last opportunity

APR-20-93 TUE 15:48 ADELPHIA FRONT ROYAL 17036352068 P.02 PROGRAMING DEPT ID:814 274 9823 APR 19'93 15:13 No.031 P.05

EXHIBIT 4

SOUTH BAY CABLEVISION

AN INTERMEDIA COMPANY

William L. Haggarty General Manager

VIA CERTIFIED MAIL

April 30, 1993

Brian Holton Station Manager KTSF-TV (26) 100 Valley Dr. Brisbane, CA 94005

Re: Notice of KTSF-TV (26) Ineligibility for Carriage as a Must-Carry Station

Dear Mr. Holton:

In accordance with Section 76.58(d) of the Rules promulgated by the Federal Communications Commission ("FCC") pursuant to Section 4 of the Cable Television Consumer Protection and Competition Act of 1992, a cable operator must notify all local commercial television stations which may not be entitled to carriage because such station either (i) fails to meet the standards for delivery of a good quality signal to the cable systems' principal headend, or (ii) such carriage may increase the cable operator's copyright liability.

Per our investigation, we hereby notify you that KTSF-TV (26) is not entitled to carriage because your station fails to meet the standards for delivery of a good quality signal to our principal headend for South Bay Cable Vision's Milpitas Mountain View system, which is located at 2700 Scott Blvd., Santa Clara, CA. In compliance with Section 76.61(a) of the FCC's Rules, attached please find a list of the equipment used to make the signal quality measurements, as well as the point of measurement and a list and detailed description (i.e. make, model and age) of the reception and over-the-air signal processing equipment used to make the Initial measurements, including sketches and a description of the methodology used for processing the signal.

Consistent with the foregoing investigation, and pursuant to Section 76.60 of the FCC's Rules, we are not obligated to provide carriage, nor is KTSF-TV (26) entitled to exercise any must-carry rights on South Bay Cable Vision's Milpitas, Mountain View system unless KTSF-TV (26) bears the costs associated with delivering a good signal to our principal headend.


Although you are presently incligible for carriage as a must-carry station under the I'CC's Rules, we are currently carrying KTSF-TV (26). In order to continue carrying your station, we must have your retransmission consent. Attached is a form which we have prepared for that purpose. If you will execute this form and return it to us, we will, at our discretion, continue to carry KTSF-TV (26) with your consent to do so.

Thank you for your attention to this matter.

William L Haggarty

2700 Scott Boulevard
Santa Clara, CA 95050 (408) 727-5295 FAX (408) 988-3723

Receive 5 5-4-93 1 . -



LIST OF EQUIPMENT

WAVETEK SAM IV SERIAL 2343102 (CALIBRATED 1-8-92)
GE 20" STEREO MONITOR
RADIO SHACK MODEL VU-190 ANTENNA
STANDARD 300/75 \(\text{MATCHING TRANSPORMER} \)
A 20' TELESCOPING MAST FULLY EXTENDED
100' OF RG-6 CABLE WITH SNAP & SEAL CONNECTORS

STATION KTSF (26)

SIGNAL REQUIRED -49 BM

SIGNAL RECORDED -59 BM

EXHIBIT 5



Executive Office:

270 South Service Road, P.O. Box 1355, Melville, N.Y. 11747 516-777-8855 Studio: 315 Wading River Hollow Road, Ridge, New York 11961

516-924-5000

FAX LETTER

David Donovan INTV Fax # 202/887-0950

Dear David:

This will reiterate the unbelievable problems we're already having with Cablevision in our efforts to get "must-carry" in our ADI. Quite simply, they are doing everything possible to stall and delay our efforts to get them a signal. It appears that they believe if we cannot get them a signal by June 2nd, then we lose our opportunity for must-carry.

They are vague, non-cooperative and never give a straight answer. We are attempting to provide a signal to their

EXHIBIT 6

WYVNFOX60



120 Industrial Drive, P.O. Box A Chambersburg, Pennsylvania 17201 717/263-8591

April 26, 1993

WYVN Ms. Carl LaFever l Discovery Place Martinsburg, WV 25401

Dear Ms. LaFever:

This letter is being sent to you pursuant to the provisions of Section 76.58(d) (2) of the Rules of the Federal Communications Commission and constitutes notice that our cable system's carriage of the signal of Station W Y V N may cause an increased copyright liability for Time Warner Cable of Chambersburg.

We are prepared to discuss our findings with you at a mutuallyconvenient time. Please contact the undersigned with any questions concerning this notice or the tests.

Sincerely,

Samuel K. Schultz, Jr. (LD m)

General Manager

SKS/jle

EAST TENNESSEE CABLEVISION

